5 Howarder 1965

Mr. Raymond E. Hamilton, Account Manager Marketing Department Chesopeake and Potomes Dalayhone Company 930 H Street, Horthwest Washington, B. C.

Dear Mr. Hemilitons

STATINTL

This office is presently making a study of future space requirements and would like to have an estimate of the space required for a limit lime addition to the main switchframe located in the Bendquarters Building.

It is requested that this information be based on the following three essemptions:

- (a) The required additional space would be contiguous to the existing suitchfrom room.
- (b) The required additional space would be located classifiers in the Headquerters Building.
- (c) The required additional space would be in another building located on the Headquarters grounds. It is our essumption that the buildings in question would be inter-connected via a pedastrian type passagement through which trusting facilities could be routed.

Your prompt reply to this impairy will be greatly appreciated.

Yeary truly years,

STATINTL

Chief, Talephone Panilities Branch

Distribution:

Orig - Addressee

1 - Buildings & Grds. - Hqs. Mdg.

1 - Chrono

STATINTL

OL/ISD/TFF Color (5 Nov. '65)

## Samtized: 6 Approved From Role 364, CIA-RDP78-04787A000100130002-0

930 H STREET, NORTHWEST WASHINGTON, D. C. 20001

> AREA CODE BGG TELEPHONE 637-0900

November 24, 1965

STATINTL

Chief, Telephone Pacilities Branch' Centeral Intelligence Agency Washington, D. C.

STATINTL

STATINTL With referrance to your letter of Movember 5, 1965, relative to space requirements for a line addition to the Agency's P.B.I. the following information is offered.

STATINTL

- A. If located adjacent to the existing switchframe room approximately sequence feet of floor space would be required.
- B. For both technical and practical reasons we would be extremely reluctant to locate additional equipment elsewhere in the same building except immediately above or below the existing frameroom. The same amount of floor space would be required as in (A) above regardless of location.

STATINTL

C. Locating the equipment in another building on the same premises as the existing frameroem would also require approximately square feet of floor space, but again we would be extremely relustant to do this.

Centrally lecated P.B.I. equipment eliminates possible sources of trouble and facilitates locating any that occur. It also reduces the amount of time required for connecting and disconnecting lines and for performing other functions such as restricting, unrestricting, intercepting and placing lines on register test.

If the P.B.I. equipment had to be separated we would less the advantages mentioned above, and, having never provided such an arrangement, it is difficult to determine the problems it might create.

If additional information is required please het me know.

Very truly yours,

R. B. Hamilton

Sanitized - Approved For Release : CIA-RDP78-04787A000100130002-0